



# BID BULLETIN



## Upcoming Projects from Public Works–Engineering

### General Information

The City of Wichita receives bids at the Purchasing office (455 N.Main, 12th Floor) up to 10:00 a.m. on the Friday specified for each project in this bulletin. All bids received online and/or on paper will thereafter be publicly opened, read aloud, and considered by the Board of Bids and by City Council. The Wichita City Council reserves the right to reject any and all bids.

Plans & Specifications for these projects are generally available 10 days prior to the bid date unless otherwise specified. All work is to be done under direction and supervision of the City Manager and according to the plans & specifications on file in the City Engineer's Office. Bidders are required to include a bid bond in the amount of five percent (5%) with each bid.

Requests for the bid documents & plans should be directed to QuikPrint (942-2208). Other questions should be directed to the project Engineer (268-4501).

The successful bidder may contact Kim Pelton (268-4499) for extra sets of plans/specs.

**NOTE: All information contained herein is subject to change.**

### SWS PROJECT

#### **WVCLFP Project Diversion Structure Repairs** 468-84766 869001

**Bid Date: 10-02-15; Award Date: 10-06-15**

#### **LUMP SUM BID ITEMS - Control Structure I**

By-pass works (siphon pipe, pumps, etc.)	1	LS
Cofferdam Works	2	LS
Siphon Pool Excavation	1,000	cy
Concrete Inspection Preparation	1	LS
Nose Wall Armor	100	lf
Site Restoration	1	LS
Project Seeding	2	ac

#### **MEASURED QTY BID ITEMS - Control Structure I**

Sawcut Existing Nosewall	30	lf
Replace Existing Nosewall	54	lf
Repair Eroded Box Culvert Floor	550	sf
Grout base of culvert floor	15	cy
Energy Dissapators	1.5	cy
Repair/replace dumped rip-rap for structure	15	tn
Repair cracks in walls outside	20	lf
Repair cracks in walls inside	20	lf
Repair deteriorated nosewall	1	cy
Erosion Control BMP (Silt Barrier)	850	lf
Erosion Control BMP (Stabilized Entrance)	2	ea
Erosion Control Blanket	9,680	sy

#### **LUMP SUM BID ITEMS - Control Structure II**

By-pass works (siphon pipe, pumps, etc.)	1	LS
Cofferdam Works	2	LS
Siphon Pool Excavation	1,000	cy
Concrete Inspection Preparation	1	LS
Nose Wall Armor	75	lf
Site Restoration	1	LS
Project Seeding	2.5	ac

#### **MEASURED QTY BID ITEMS - Control Structure II**

Sawcut Existing Nosewall	15	lf
Replace Existing Nosewall	27	lf
Repair Eroded Box Culvert Floor	375	sf
Grout base of culvert floor	10	cy
Energy Dissapators	1.5	cy
Repair/replace dumped rip-rap for structure	15	tn
Repair cracks in walls outside	15	lf
Repair cracks in walls inside	10	lf
Repair deteriorated nosewall	2	cy
Erosion Control BMP (Silt Barrier)	1,355	lf
Erosion Control BMP (Stabilized Entrance)	2	ea

Continued in next column

August 27, 2015

#### **WVCLFP Project Diversion Structure Repairs**

**Bid Date: 10-02-15; Award Date: 10-06-15**

#### **MEASURED QTY BID ITEMS -Control Structure II**

Continued

Erosion Control Blanket	9,680	sy
-------------------------	-------	----

#### **LUMP SUM BID ITEMS - Control Structure IV**

Cofferdam Works	4	LS
Concrete Inspection Preparation	1	LS
Nose Wall Armor	450	lf
Site Restoration	1	LS
Project Seeding	3	ac
By-Pass Channel Excavation	1,745	cy
By-Pass Channel Fill	1,745	cy
Rip-rap	175	tn

#### **MEASURED QTY BID ITEMS -Control Structure IV**

Sawcut Existing Nosewall	135	lf
Replace Existing Nosewall	243	lf
Repair Eroded Box Culvert Floor	1,920	sf
Grout base of culvert floor	50	cy
Energy Dissapators	5	cy
Repair/replace dumped rip-rap for structure	60	tn
Repair cracks in walls outside	100	lf
Repair cracks in walls inside	100	lf
Repair deteriorated nosewall	15	cy
Erosion Control BMP (Silt Barrier)	1,185	lf
Erosion Control BMP (Stabilized Entrance)	2	ea
Erosion Control Blanket	14,520	sy

#### **LUMP SUM BID ITEMS - Control Structure V**

By-pass works (siphon pipe, pumps, etc.)	1	LS
Cofferdam Works	2	LS
Siphon Pool Excavation	250	cy
Concrete Inspection Preparation	1	LS
Sheet Pile Weir	7,735	sf
Sheet Pile Weir Waler	225	lf
Site Restoration	1	LS
Project Seeding	2	ac

#### **MEASURED QTY BID ITEMS-Control Structure V**

Repair Eroded Box Culvert Floor	95	sf
Grout base of culvert floor	1	cy
Repair/replace dumped rip-rap for structure	5	tn
Repair cracks in walls outside	20	lf
Repair cracks in walls inside	20	lf
Erosion Control BMP (Silt Barrier)	885	lf
Erosion Control BMP (Stabilized Entrance)	2	ea
Erosion Control Blanket	7,260	sy

Page 1 of 1

A minority/women-owned business is 51% owned and controlled by a minority or women. MBE/DBE classes are defined as: Asian (A) American Indian (AI) Black (B) Hispanic (H) and Women-owned (WO). We appreciate your cooperation in providing this information.